

User Manual



Please read operating manual before installation and operation.

Drawell International Technology Limited
Chongqing Drawell Instrument Co., Ltd.
Shanghai Drawell Scientific Instrument Co.,Ltd.

Chongqing Center : Suite 2705,Building No.12,Shiyou Road No.1, Yuzhong District,
Chongqing, China.

Shanghai Office : Suite 1117,Lane561 XiuChuan Rd.,PuDong New
Area,Shanghai,China

Homepage : www.drawell.com.cn

Tel : 0086-023-63268643

Email : sales05@drawell.com.cn

Outline

Thank you for purchasing **YP** series electronic balance.

The YP models are high performance electronic balances that we confidently recommend based on 20 years of precision balance manufacture. While there models are of course capable of fast and accurate weighing, the YP models all work on high precision strain gauge load cell which implements high speed stabilization and high reliability.

The YP series balances also feature operation keys, improving operating convenience and making the balances easier to use.

These balances also feature a variety of other functions that make it more convenient for customers to use for their own applications, including the Window Direct communication function, which enables measuring results to be transferred to a PC without installing any software.

To ensure that you can make full use of the performance and function of your YP series balances, read this instruction manual carefully and use the balance correctly in accordance with the directions in the manual. When you have finished reading the manual, keep it in a safe place together with the balance so that you can refer to it at any time.

YP series precision balance work on high precision strain gauge load cell which implements high speed stabilization and high reliability.

Specifications,

Model No. (YP)	1000	2000	3000	4000	5000
Max. Capacity (g)	1000	2000	3000	4000	5000
Tare Range (g)	0-1000	0-2000	0-3000	0-4000	0-5000
Readability	1g				
Pan Size (mm)	143*192mm				
Dimensions (LxWxH)	280x180x80mm				
Power supply	AC 110-120V/220-240V				

Model No. (YP)	10001	20001	30001	40001	50001
Max. Capacity (g)	1000	2000	3000	4000	5000
Tare Range (g)	0-1000	0-2000	0-3000	0-4000	0-5000
Readability	0.1				
Pan Size (mm)	143*192mm				
Dimensions (LxWxH)	280x180x80mm				
Power supply	AC 110-120V/220-240V				


Model No. (YP)	2002	3002	5002	6002	10002	20002
Max. Capacity (g)	200	300	500	600	1000	2000
Tare Range (g)	0-200	0-300	0-500	0-600	0-1000	0-2000
Readability	0.01					
Pan Size (mm)	133*182mm					
Dimensions (LxWxH)	280x180x80mm					
Power supply	AC 110-120V/220-240V					

Operating Temperature Range: 5-35 Degree Centigrade


Moisture: 50-85%

1 BEFORE WEIGHING

Main body



Name and Function of the Components



Operation Keys

Key	During Weighing	
	Press once and Release	Press and hold for a while
ON/OFF	Turn on or turn off the balance	—
COU	Select the counting function	—
TAR/CAL	Tare the balance(setting it to zero)	Performs calibration
UNIT	Select the unit	—

Choosing the Installation Site

The measuring performance of the balance is greatly influenced by the environment where it is installed.

Observe the following points to ensure safe and accurate weighing.

Caution



Prohibitions

Do not use the balance anywhere exposed to explosive, combustible or corrosive gases.

This could cause fire or trouble.





Instructions

Use the correct power supply and voltage with the balance.

Using an incorrect power supply or voltage with the balance will lead to fire or trouble with the balance.

Note also that if the power supply or voltage is unstable or if the power supply capacity is insufficient, it will not be possible to obtain satisfactory performance from the balance.


Precautions on Use



Prohibitions

Avoid locations where the balance will be exposed to any of the following.


▫ Air flow from an air conditioner, ventilator, door or window



▫ Extreme temperature changes



▫ Vibration from surroundings or nearby equipment



☞Direct sunlight



☞Dust, electromagnetic waves or a magnetic field



Instructions

Install the balance on a strong and stable flat table or floor.

Placing the balance in an unstable site could lead to injury or trouble with the balance. When selecting the installation site, take into account the combined weight of the balance and the item to be weighed.

Unpacking and Delivery Inspection

Check that all of the items indicated below are included in the package, and that nothing has been damaged.

[1] Main Body

[2] Pan

[3] Introduction Manual

[4] Adapter


Turning the Power On

1 Insert the plug of the Power Cord into the DC IN connector on the back of the balance.

2 Connect the Power Cord to the power outlet.

3 Press "ON".

The display will automatically go through the changes indicated below.



Warming Up

Before performing span calibration on the balance or measuring its accuracy, you must ensure that it is in a stable state.

When stabilizing the balance, it is important that its temperature is stable.

Putting the balance in weighing mode and leave it with the power on for at least half an hour in advance of calibration.

This is called "warming up".

Performing Span Calibration

Always perform span calibration for a balance after moving it. Weights are required for external calibration balances.

Before performing span calibration, warm up the balance in advance.

Also, carry out the adjustment at a location where there are few people moving around and there is no air flow or vibration.

1 Press “CAL”

The weight value will flash.


The calibration record is being output. When the output has finished, span calibration will start automatically

2 Place the calibration weight on the pan.

Wait until the flashing weight value display changes to a steady 500.00.

3 Take the weight off the pan.

“0.00” will be displayed and the balance will return to the weighing mode



USING THE BALANCE

- 1 Enter the weighing mode
- 2 Place a container on the pan.
- 3 Once the display has stabilized, press “zero/tar”.
The indication changes to zero.
- 4 Insert the sample into the container.
- 5 When the display has stabilized, (the stability mark) lights up, read the display.


Selecting the Display

Switching Units

You can display different units from among those set to be available.

1 press “UNIT” in the weighing mode.

Repeatedly pressing this key will cycle you through the registered units.



Drawell International Technology Limited
Chongqing Drawell Instrument Co., Ltd.
Shanghai Drawell Scientific Instrument Co.,Ltd.

Chongqing Center : Suite 2705,Building No.12,Shiyou Road No.1, Yuzhong District,
Chongqing, China.

Shanghai Office : Suite 1117,Lane561 XiuChuan Rd.,PuDong New
Area,Shanghai,China

Homepage : www.drawell.com.cn

Tel : 0086-023-63268643

Email : sales05@drawell.com.cn