Packing List for DW-AA4530F

Accessories List Of AAS

Sr.	Description	Qty.
1	Polyethylene pipe φ12*8	3
2	Nylon pipe φ6*1	20
3	O-ring φ6*1.9	6
4	O-ring φ10*2	10
5	O-ring φ14*2	6
6	O-ring φ17*2.65	3
7	O-ring φ31*3.5	3
8	Fuse 3A	3
9	Fuse 0.5A	4
10	Nut	4
11	Threaded sleeve	8
12	Bush	8
13	Sealed gasket	8
14	Light board	1
15	Connector of acetylene regulator	1
16	O-ring φ55*3.1	3
17	Wrench 8*10	1
18	Wrench 12*14	1
19	Wrench 17*19	1
20	Screwdriver（“+”）	1
21	Dongle	1
22	Igniter assembly	1
23	Cable	1
24	Power line	1
25	Cu lamp	1
26	Atomizer	2
27	Workstation software	1
28	USB2.0 to 232 serial cable	1
29	Air dryer and filter assembly	1
30	Holder of air dryer and filter assembly	1
31	Main instrument	1
32	Computer	1
33	Printer	1
34	Air compressor	1