

Packing list

DW-180B Atomic Absorption Spectrophotometer

Item No.	Description	Q'ty	Remarks
01	Main unit	1unit	
02	Packing list	1copy	
03	Certificate of Quality	1copy	
04	Cautions	1copy	
05	USB flash disk	1pc	Include Software, Operation Manual, Instruction manual of Workstation, Operation flow chart
06	Safety Precautions	1 copy	
07	Power cable of main unit	1pc	
08	Comm. Cable Connecting Main Unit to PC	1pc	
09	Instrument Cover	1pc	
10	Rubber Tubing $\Phi 8 \times 3$ (red)	10m	For C ₂ H ₂
11	PU Tubing $\Phi 6 \times 1$ (blue)	0.8m	For Air
12	PU Tubing $\Phi 8 \times 1$ (blue)	5m	For Air
13	Fluid Tubing $\Phi 10 \times 1$ (transparent)	1.5m	For liquid waste
14	Gas water separator	1set	With holder and screws
15	$\phi 10-16$ Fitting	3pcs	
16	Hollow Cathode Lamps -Cu、Hg	1pc/each	
17	Fuse 3A-5 \times 20	2pcs	Fixed on the instrument
18	Reading pedal group	1set	
19	High efficiency glass nebulizer	1set	
20	Explosion Prevention Film	5pcs	
21	Inner-hexagon spanner 2.5mm、3mm	1pc/each	
22	5"Crosshead Screwdriver 、 Line-end Screwdriver	1pc/each	
23	MQK1 Gas Sensor	2pcs	
24	Flame Cleaning Card	5pcs	

Packing:

Inspector: